

**PARTS LIST FOR #6062
CHEVY V8 LAKEWOOD CAN NO CONTAINMENT
HOLES MIDPLATE BOLT IN FOR 62-67 CHEVY II**

<u>NO.</u>	<u>QTY</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>
1.	1	2047	Chevy V8 Lakewood can no containment holes
2.	1	2374	Midplate frame adapter driver side
3.	1	2375	Midplate frame adapter passenger side
4.	4	3245	Locknut 3/8-16 stainless steel
5.	8	3253	Stainless 3/8 washer 25/64 x 1"
6.	4	3434	Buttonhead allen 3/8-16 x 1 1/4 stainless

Refer to your Installation Guide for assembly procedure.

The perimeter of the midplate may not match non-Lakewood style clutch cans. Do not use this midplate with non-Lakewood style cans if the can perimeter is larger than the midplate or, if any bolt holes do not have adequate material around them.

Revision Date: December 14, 1999



**PARTS LIST FOR #6062
CHEVY V8 LAKEWOOD CAN NO CONTAINMENT
HOLES MIDPLATE BOLT IN FOR 62-67 CHEVY II**

<u>NO.</u>	<u>QTY</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>
1.	1	2047	Chevy V8 Lakewood can no containment holes
2.	1	2374	Midplate frame adapter driver side
3.	1	2375	Midplate frame adapter passenger side
4.	4	3245	Locknut 3/8-16 stainless steel
5.	8	3253	Stainless 3/8 washer 25/64 x 1"
6.	4	3434	Buttonhead allen 3/8-16 x 1 1/4 stainless

Refer to your Installation Guide for assembly procedure.

The perimeter of the midplate may not match non-Lakewood style clutch cans. Do not use this midplate with non-Lakewood style cans if the can perimeter is larger than the midplate or, if any bolt holes do not have adequate material around them.

Revision Date: December 14, 1999

